



NOTES

1. DIMENSIONS ARE TO BE READ AND TO BE CHECKED OFF.
2. CONNECTIONS TO OTHER ALL DIMENSIONS BEHIND EXECUTION OF WORKING LINE DIMENSIONS SET AS LOCAL DIMS.
3. REFER TO THE DIMENSIONS SET AS LOCAL DIMS.
4. ALL DIMENSIONS ARE TO BE CHECKED OFF AND TO BE CONFIRMED AS TO BE CORRECT TO THE GABLE END.
5. TO BE CHECKED OFF TO THE GABLE END.
6. TO BE CHECKED OFF TO THE GABLE END.
7. TO BE CHECKED OFF TO THE GABLE END.
8. TO BE CHECKED OFF TO THE GABLE END.
9. TO BE CHECKED OFF TO THE GABLE END.

SR MEMBER SIZE SILL LVL INTEL LVL

1.	RS	300X1200	101.40	102.80
2.	W			

COL C-1
VERT. ST. - form dia for shoes.
TIES - form dia for shoes @ 250mm oc

COL C-2
VERT. ST. - form dia for shoes.
TIES - form dia for shoes @ 250mm oc

COL C-1
VERT. ST. - form dia for shoes.
TIES - form dia for shoes @ 250mm oc

COL C-2
VERT. ST. - form dia for shoes.
TIES - form dia for shoes @ 250mm oc

SEC AT XX
ELEVATION AT GABLE END

SEC AT YY
ELEVATION AT GABLE END

TERRACE PLAN

KEY PLAN

STRUCTURE

CONFIDENTIAL

PROJECT: SHED FOR R.O.
CLIENT: CONFIDENTIAL
PROJECT NO.: RLL/02/001/150503

KEY PLAN
TERRACE PLAN
ELEVATION AT GABLE END
ELEVATION AT GABLE END
SEC AT XX
SEC AT YY

ENGINEER: CONFIDENTIAL
DRAWN BY: V.P.

SCALE: 1:50
DATE: 15/05/2003
DWG. NO.: